

From: [Daly, Keith](#)
To: [document.control;](#)
cc: [Peppers, Nicki; Gleason, Tonja;](#)
Subject: FW: Bubble ring roller RFI# 001
Date: Tuesday, January 18, 2011 5:33:13 PM
Attachments: [RFI 001.doc](#)

Document control,

Please file under contract 8078, Request for Information #001.

Keith Daly
Assistant Business Manager

[Columbia River Crossing Project | mailto:dalyk@columbiarivercrossing.org](mailto:dalyk@columbiarivercrossing.org)
700 Washington St. Suite 300, Vancouver, WA 98660
office: 360.816.8870 | Office: 503.256.2726 Ext. 8870
Fax: 360.737.0294

From: Kevin Culbert [<mailto:kevinc@americanconstco.com>]
Sent: Tuesday, January 18, 2011 4:59 PM
To: Daly, Keith
Subject: FW: Bubble ring roller RFI# 001

Keith:

Rainier Welding is sourcing their materials for the bubble system and cannot find neoprene rollers as specified that can be delivered in time. They are requesting that they be allowed to fabricate the rollers out of UHMW. I can formalize the RFI, but I wanted to get it to you as soon as possible.

Kevin

From: Bob Webster [<mailto:b.webster@rainierwelding.com>]
Sent: Tuesday, January 18, 2011 4:30 PM
To: 'Kevin Culbert'
Subject: Bubble ring roller RFI# 001

Kevin, attached is our RFI#001 regarding substituting UHMW for the neoprene rollers.

Bob Webster
Rainier Welding, Inc.

19020 NE 84th Street
Redmond WA 98053-9406
Phone: 425-868-1300
FAX: 425-868-8872
E-mail: b.webster@rainierwelding.com