02798 1 of 1

From: jilaynejordan@yahoo.com

To: <u>Draft EIS Feedback</u>;

CC:

Subject: DEIS Document Viewer Feedback

Date: Friday, June 20, 2008 11:47:54 AM

Attachments:

From: Jilayne Jordan Zip Code: 98660

Address: 708 W. Fourth Plain Blvd.

City: Vancouver

State: WA

E-Mail: jilaynejordan@yahoo.com

Section: Summary

Page: S-16

Comment or Question:

Keeping either of the old spans is unacceptable. The bridge lifts are one of the main causes of congestion on this bridge currently. Additionally, simply retrofitting these aged structures will not make them sufficiently safe.

